



PCS-1 & PCS-2 (PRE-6/96) PART NUMBERS

#	Part #	Description	Qty.
1	138	Handle Grip	1
2	103-2	Clamp Handle	1
3	101-2	Movable Jaw	1
4	107-CS	Clevis Pin	2
5	107-2	5/16" E-Clip	2
6	468G	Jaw Cover Set (Includes Circlips)	1
7	467-1	Circlip	4
8	110B	Linkage	1
9	111A-6	Spring	1
10	112A-CS-R	Linkage Pivot	1
11	113A	5/16-18 Jam Nylok Nut	1

#	Part #	Description	Qty.
12	112B-R	Linkage Pivot Knob	2
13	102-2	Rotating Shaft & Jaw	1
14	190B	End Cap for Horizontal Tube	1
15	191-2G	Positioning Knob & Shaft	1
16	195	Bench Mount Weldment (PCS-2 only)	1
17	185-2	Upright Weldment (PCS-1 only)	1
18	226-2	1/4-20 Jam Nylok Nut (PCS-1 only)	2
19	187-2D	1/4-20 x 2 Hex Head Bolt (PCS-1 only)	2
20	187-2C	Curved Leg (PCS-1 only)	2
21	190-2	Leveling End Cap (PCS-1 only)	2
22	104	Work Tray (PCS-1 only) (Optional)	